

GUJARAT TECHNOLOGICAL UNIVERSITY

BE - SEMESTER-VIII(OLD) • EXAMINATION - WINTER 2017

	•	t Code:182					Date: 07-11-20)17					
Tiı	ne: (truction 1. 2.	02:30 pm tons: Attempt a Make suit	uality Assuranto 05:00 pm Il questions. able assumptions the right indicate	wherever	necessary.		Total Marks:	70					
Q.1	(a) (b)		e classification of points of Deming		-	vith suitab	ole examples.	07 07					
Q.2	(a) (b)	Define Reliability. Explain its importance and state its elements. 1. Explain Normal Distribution curve and its significance. 2. Define Quality Assurance and explain it in detail. OR											
	(b)		table control charmine the control li		ollowing data a		our comments.	07					
		Lot No.	No. of defects	Lot No.	No. of defects	Lot No.	No. of defects						
		1	80	8	42	15	77						
		2	92	9	56	16	54						
		3	58	10	63	17	69						
		4	65	11	43	18	47						
		5	81	12	58	19	56						
		6	67	13	61	20	51						
		7	55	14	50								
Q.3 Q.3	(a) (b) (a)	working pa Explain the 1. Imp 2. Cer 3. Con Explain the	attern. e following terms cossible event tain event mplementary even	with one	suitable examp	ole for eac	18 47 19 56 20 51 of formation and its 07						
	(b)			les: 1 . M	TTF 2. Rando	om events	3. Kolmogorov's	07					
Q.4	(a)	1. Cor	e following ISO90 ntract Review sign Review	001 clause	es;			07					



FirstRanker.com

Firstrop k Following table illustrates which is the second to the company to days. machine. A sample of six blocks was taken each day for eight consecutive days in series to draw this table. The block specification as designed is 15.75 +/- 0.1 mm. Construct X-bar and Range Charts from the data available and comment on the statistical stability of the process. Also comment on the chart patterns observed. Calculate process capability index Cp and comment suitably regarding the capacity of the process to produce the components as per the design specification.

1 st Day	2 nd Day	3 rd Day	4 th Day	5 th Day	6 th Day	7 th Day	8 th Day
15.77	15.80	15.77	15.79	15.75	15.78	15.76	15.76
15.80	15.78	15.78	15.76	15.78	15.76	15.78	15.79
15.78	15.76	15.77	15.79	15.78	15.73	15.75	15.77
15.73	15.70	15.77	15.74	15.77	15.76	15.76	15.72
15.76	15.81	15.80	15.82	15.76	15.74	15.81	15.78
15.75	15.77	15.74	15.76	15.79	15.78	15.80	15.78

 $(A_2=0.483.$ $D_4=2.004$, $D_3=0$, $D_2=2.534$)

OR

Explain the concept of 'six sigma' with the help of steps involved in the 0.4 (a) application of the same.

07

07

(b) In a manufacturing process, the number of defectives found in the inspection of 15 lots of 400 items each are given below:

Date 2 3 5 4 6 8 9 10 11 12 13 14 15 No. of 2 5 0 14 3 18 8 3 0 1 0 6 0 0 6 defectives

Determine the control limits for np chart and state whether the process is in control. Carry out one iteration if some points are falling outside the control limits and find out new limits.

Explain the process of Audit in line with ISO9001 registration. **Q.5**

07

Explain bath tub curve with the help of a suitable example.

07

OR

(a) Evaluate the statements: **Q.5**

07

- 1. 'Quality of design is dependent on the application of the component.'
- 2. 'Quality control and quality assurance is the same.'
- (b) Explain the concept of sampling and risks associated with sampling.

07
