

Code No: NR/RR210205

NR/RR

Set No. 2

II B.Tech I Semester Examinations, November 2010

ELECTRO MECHANICS - I

Electrical And Electronics Engineering

Time: 3 hours

Max Marks: 80

Answer any FIVE Questions

All Questions carry equal marks

1. (a) Explain the purpose of laminating the armature core of a d. c. machine.
 (b) The diameter of a commutator ring of a lap wound d. c. motor is 25 cms. The brush width is 1.8 cm and width of mica insulation is 0.2 cm. If the speed of the motor is 200 rpm, determine the time of commutation. [6+10]
2. (a) Describe any one laboratory test procedure to separate the losses in a DC machine?
 (b) In a DC machine the total iron loss at the rated speed and excitation is 9KW on keeping excitation unaltered but reducing speed by 30%, the total iron loss was found to be 5KW. Calculate hysteresis and eddy current losses at
 - i. full speed; and
 - ii. half the rated speed with the same excitation. [8+8]
3. (a) Develop the general expression for the speed of a motor in terms of supply voltage, armature resistance and flux per pole.
 (b) Discuss the applications of series motors and compound motors. [8+8]
4. (a) Write a note on series-parallel Speed Control method of D.C. Series Motors.
 (b) A 4 pole, 250V, d.c. series motor has a wave wound armature with 496 conductors. Calculate:
 - i. The gross torque
 - ii. The speed
 - iii. The output torque
 - iv. The efficiency, if the motor current is 50A
 - v. The value of flux per pole under these conditions is 22 mwb and the corresponding iron, friction and vintage losses totaling 810 w. Armature resistance = 0.19Ω field resistance = 0.14Ω [8+8]
5. (a) Explain the principle of action of commutator in a d. c. generator.
 (b) Define
 - i. front pitch
 - ii. back pitch
 - iii. coil span and
 - iv. commutator pitch as applied to d. c. armature windings and indicate the above on the diagram of a wave winding. [8+8]

Code No: NR/RR210205

NR/RR

Set No. 2

6. A 250V, 50KW shunt generator has 1000 turns on each pole of its field winding. On no load a current of 3.5A in the field winding produces a terminal voltage of 250V, but on full load the shunt current has to be increased to 5A for the same terminal voltage at the same speed. Calculate number of series field turns per pole required for level compounding. [16]
7. (a) Why is a starter necessary for a dc motor? What is the difference between 3 point and 4 point starters?
- (b) Calculate the values of resistance elements for a 6-stud starter. The maximum current at starting is not to exceed 20A for a 200V shunt motor. The armature resistance is 0.5Ω . What is the value of minimum current? [8+8]
8. Obtain an expression for torque of a reluctance motor shown in the figure3 in terms of direct axis and quadrature axis reactances. [16]




Figure 3

Code No:NR/RR210205

NR/RR

Set No. 4

II B.Tech I Semester Examinations, November 2010

ELECTRO MECHANICS - I

Electrical And Electronics Engineering

Time: 3 hours

Max Marks: 80

Answer any FIVE Questions

All Questions carry equal marks

1. A 250V, 50KW shunt generator has 1000 turns on each pole of its field winding. On no load a current of 3.5A in the field winding produces a terminal voltage of 250V, but on full load the shunt current has to be increased to 5A for the same terminal voltage at the same speed. Calculate number of series field turns per pole required for level compounding. [16]
2. (a) Write a note on series-parallel Speed Control method of D.C. Series Motors.
 (b) A 4 pole, 250V, d.c. series motor has a wave wound armature with 496 conductors. Calculate:
 - i. The gross torque
 - ii. The speed
 - iii. The output torque
 - iv. The efficiency, if the motor current is 50A
 - v. The value of flux per pole under these conditions is 22 mwb and the corresponding iron, friction and vintage losses totaling 810 w. Armature resistane = 0.19Ω field resistance = 0.14Ω [8+8]
3. (a) Explain the principle of action of commutator in a d. c. generator.
 (b) Define
 - i. front pitch
 - ii. back pitch
 - iii. coil span and
 - iv. commutator pitch as applied to d. c. armature windings and indicate the above on the diagram of a wave winding. [8+8]
4. (a) Develop the general expression for the speed of a motor in terms of supply voltage, armature resistance and flux per pole.
 (b) Discuss the applications of series motors and compound motors. [8+8]
5. (a) Explain the purpose of laminating the armature core of a d. c. machine.
 (b) The diameter of a commutator ring of a lap wound d. c. motor is 25 cms. The brush width is 1.8 cm and width of mica insulation is 0.2 cm. If the speed of the motor is 200 rpm, determine the time of commutation. [6+10]
6. (a) Describe any one laboratory test procedure to separate the losses in a DC machine?

Code No: NR/RR210205

NR/RR

Set No. 4

- (b) In a DC machine the total iron loss at the rated speed and excitation is 9KW on keeping excitation unaltered but reducing speed by 30%, the total iron loss was found to be 5KW. Calculate hysteresis and eddy current losses at
- full speed; and
 - half the rated speed with the same excitation.
- [8+8]
7. Obtain an expression for torque of a reluctance motor shown in the figure3 in terms of direct axis and quadrature axis reactances. [16]




Figure 3

8. (a) Why is a starter necessary for a dc motor? What is the difference between 3 point and 4 point starters?
- (b) Calculate the values of resistance elements for a 6-stud starter. The maximum current at starting is not to exceed 20A for a 200V shunt motor. The armature resistance is 0.5Ω . What is the value of minimum current? [8+8]

Code No: NR/RR210205

NR/RR

Set No. 1

II B.Tech I Semester Examinations, November 2010

ELECTRO MECHANICS - I

Electrical And Electronics Engineering

Time: 3 hours

Max Marks: 80

Answer any FIVE Questions
All Questions carry equal marks

1. Obtain an expression for torque of a reluctance motor shown in the figure 3 in terms of direct axis and quadrature axis reactances. [16]




Figure 3

2. (a) Develop the general expression for the speed of a motor in terms of supply voltage, armature resistance and flux per pole. [8+8]
(b) Discuss the applications of series motors and compound motors.
3. (a) Write a note on series-parallel Speed Control method of D.C. Series Motors.
(b) A 4 pole, 250V, d.c. series motor has a wave wound armature with 496 conductors. Calculate:
i. The gross torque
ii. The speed
iii. The output torque
iv. The efficiency, if the motor current is 50A
v. The value of flux per pole under these conditions is 22 mwb and the corresponding iron, friction and vintage losses totaling 810 w. Armature resistane = 0.19Ω field resistance = 0.14Ω [8+8]
4. (a) Explain the purpose of laminating the armature core of a d. c. machine.
(b) The diameter of a commutator ring of a lap wound d. c. motor is 25 cms. The brush width is 1.8 cm and width of mica insulation is 0.2 cm. If the speed of the motor is 200 rpm, determine the time of commutation. [6+10]
5. (a) Explain the principle of action of commutator in a d. c. generator.
(b) Define

Code No: NR/RR210205

NR/RR**Set No. 1**

- i. front pitch
 - ii. back pitch
 - iii. coil span and
 - iv. commutator pitch as applied to d. c. armature windings and indicate the above on the diagram of a wave winding. [8+8]
6. (a) Describe any one laboratory test procedure to separate the losses in a DC machine?
- (b) In a DC machine the total iron loss at the rated speed and excitation is 9KW on keeping excitation unaltered but reducing speed by 30%, the total iron loss was found to be 5KW. Calculate hysteresis and eddy current losses at
- i. full speed; and
 - ii. half the rated speed with the same excitation. [8+8]
7. (a) Why is a starter necessary for a dc motor? What is the difference between 3 point and 4 point starters?
- (b) Calculate the values of resistance elements for a 6-stud starter. The maximum current at starting is not to exceed 20A for a 200V shunt motor. The armature resistance is 0.5Ω . What is the value of minimum current? [8+8]
8. A 250V, 50KW shunt generator has 1000 turns on each pole of its field winding. On no load a current of 3.5A in the field winding produces a terminal voltage of 250V, but on full load the shunt current has to be increased to 5A for the same terminal voltage at the same speed. Calculate number of series field turns per pole required for level compounding. [16]

Code No: NR/RR210205

NR/RR

Set No. 3

II B.Tech I Semester Examinations, November 2010

ELECTRO MECHANICS - I

Electrical And Electronics Engineering

Time: 3 hours

Max Marks: 80

Answer any FIVE Questions
All Questions carry equal marks

1. (a) Develop the general expression for the speed of a motor in terms of supply voltage, armature resistance and flux per pole.
(b) Discuss the applications of series motors and compound motors. [8+8]
2. (a) Explain the principle of action of commutator in a d. c. generator.
(b) Define
 - i. front pitch
 - ii. back pitch
 - iii. coil span and
 - iv. commutator pitch as applied to d. c. armature windings and indicate the above on the diagram of a wave winding. [8+8]
3. Obtain an expression for torque of a reluctance motor shown in the figure 3 in terms of direct axis and quadrature axis reactances. [16]




Figure 3

4. (a) Why is a starter necessary for a dc motor? What is the difference between 3 point and 4 point starters?
(b) Calculate the values of resistance elements for a 6-stud starter. The maximum current at starting is not to exceed 20A for a 200V shunt motor. The armature resistance is 0.5Ω . What is the value of minimum current? [8+8]
5. (a) Explain the purpose of laminating the armature core of a d. c. machine.
(b) The diameter of a commutator ring of a lap wound d. c. motor is 25 cms. The brush width is 1.8 cm and width of mica insulation is 0.2 cm. If the speed of the motor is 200 rpm, determine the time of commutation. [6+10]

Code No: NR/RR210205

NR/RR**Set No. 3**

6. (a) Describe any one laboratory test procedure to separate the losses in a DC machine?
- (b) In a DC machine the total iron loss at the rated speed and excitation is 9KW on keeping excitation unaltered but reducing speed by 30%, the total iron loss was found to be 5KW. Calculate hysteresis and eddy current losses at
- i. full speed; and
 - ii. half the rated speed with the same excitation. [8+8]
7. A 250V, 50KW shunt generator has 1000 turns on each pole of its field winding. On no load a current of 3.5A in the field winding produces a terminal voltage of 250V, but on full load the shunt current has to be increased to 5A for the same terminal voltage at the same speed. Calculate number of series field turns per pole required for level compounding. [16]
8. (a) Write a note on series-parallel Speed Control method of D.C. Series Motors.
- (b) A 4 pole, 250V, d.c. series motor has a wave wound armature with 496 conductors. Calculate:
- i. The gross torque
 - ii. The speed
 - iii. The output torque
 - iv. The efficiency, if the motor current is 50A
 - v. The value of flux per pole under these conditions is 22 mwb and the corresponding iron, friction and vintage losses totaling 810 w. Armature resistance = 0.19Ω field resistance = 0.14Ω [8+8]
