

Roll No.

--	--	--	--	--	--	--	--	--	--

Total No. of Pages : 02

Total No. of Questions : 09

B.Tech.(EE / Electrical & Electronics) (2011 Onwards E-I) (Sem.-6)

COMPUTER AIDED ELECTRICAL MACHINE DESIGN

Subject Code : BTEE-605A

Paper ID : [A2339]

Time : 3 Hrs.

Max. Marks : 60

INSTRUCTIONS TO CANDIDATES :

1. SECTION-A is COMPULSORY consisting of TEN questions carrying TWO marks each.
2. SECTION-B contains FIVE questions carrying FIVE marks each and students have to attempt any FOUR questions.
3. SECTION-C contains THREE questions carrying TEN marks each and students have to attempt any TWO questions.

SECTION-A**1. Answer briefly :**

- a. How the induction motor can be designed for best power factor?
- b. What are the materials used for slip-rings and brushes in induction motor?
- c. Name few insulating materials used in transformer.
- d. Why short chorded windings are employed in induction motor?
- e. Why stepped core are generally used for transformer?
- f. Why wound rotor construction is adopted?
- g. What type of starter cannot be used for squirrel cage motors?
- h. What is the fundamental requirement of a good insulating material?
- i. Define unbalanced magnetic pull.
- j. What are the ranges of specific magnetic and specific electric loading in induction motor?

SECTION-B

2. Classify the insulating materials based on thermal considerations. Give examples for each classification.
3. Derive the output equation of a three-phase core type transformer.
4. Explain the peripheral velocity and its influence on design of machines.
5. Prove that e.m.f./turn of a single-phase transformer = $K\sqrt{Q}$, where Q = per phase kVA output of transformer.
6. What steps are taken in the design procedure to minimize crawling and cogging in case of a three-phase induction motors?

SECTION-C

7. Discuss the various factors considered when estimating the length of air-gap of a three-phase induction motor. Give the expressions used in calculations of length of air-gap.
8. Derive the expression for the number of cooling tubes required to limit the temperature rise in a three-phase transformer. Design its tank dimensions and show them pictorially.
9. Show that :
 - a. for minimum cost design of transformer, cost of iron = cost of conductor and;
 - b. for minimum copper loss, current density in primary winding = current density in secondary winding.