

## **GUJARAT TECHNOLOGICAL UNIVERSITY**

BE - SEMESTER-VI (NEW) EXAMINATION - WINTER 2018

Subject Code:2160907 Date:15/1			2/2018	
Subj	ect 1	Name:Utilization of Electrical Energy and Traction		
Time: 02:30 PM TO 05:00 PM Total Marks			rks: 70	
Instru	ction	s:		
		Attempt all questions.		
		Make suitable assumptions wherever necessary.		
	3.	Figures to the right indicate full marks.	MARKS	
0.4		A		
<b>Q.1</b>	(a)	<u>•</u>	03	
	1 2	Justify: DC shunt motor should never be started on load.  Draw labelled typical speed-time curve for main line service.		
	3	Write principle of dielectric heating.		
	(b)		04	
	, ,	•	•	
	1 2	List main causes of failure of heating elements.  State and explain in brief Lambert's cosine law.		
Q.2	(a)	•	03	
Q. <u>-</u>	` ′			
	(b) (c)	Write detail specifications of squirrel cage induction motor.  Explain different braking methods used for DC series motor.	04 07	
	(C)	OR	U7	
	(c)		07	
	( )	contact system. Describe with a neat diagram the pantograph collector.		
Q.3	(a)	Explain applications of high frequency eddy current heating.	03	
	<b>(b)</b>	Suggest suitable A.C. & D.C. drives for following applications. Give	04	
		reasons for the same. (i) Pump (ii) Hoist (Crane)		
	(c)	Explain working of LPMV lamp with necessary diagram.	07	
0.2	(-)	OR	02	
Q.3	(a) (b)		03 04	
	(c)	Draw and explain electrical circuit used in domestic refrigerator.	0 <del>4</del> 07	
Q.4	(a)	-	03	
ζ	(b)	Compare Resistance and Arc welding.	04	
	(c)	EMU has an average speed of 42 kmph on level track between stops	07	
		1400m apart. It is accelerated at 1.7 kmphps & braked at 3.3 kmphps.		
		Draw speed-time curve for run indicating all numerical values.		
0.4		OR	0.2	
<b>Q.4</b>	(a)		03	
	<b>(b)</b>	·	04	
	(c)	Explain Ajax Wyatt type induction furnace with diagram.	07	
Q.5	(a)	• • • • • • • • • • • • • • • • • • • •	03	
	<b>(b)</b>	•	04	
	(c)	Deduce the expression for the total tractive effort for propulsion of train	07	
		considering acceleration, up the gradient, to overcome resistance.  OR		
Q.5	(a)	Discuss factors affecting scheduled speed.	03	
٧.5	(b)	· · · · · · · · · · · · · · · · · · ·	03	
	(~)	parameters.	•	
	(c)	Write principle of resistance welding. Explain Butt welding.	07	

\*\*\*\*\*