



www.FirstRanker.com





9. An isometric view of a solid is shown in figure 1 below. Draw the front and top orthographic views of the solid. The dimensions may be assumed in suitable units and in proper proportion to the dimension shown in the figure 1. [15]



OR Draw the isometric view of the casting whose front and top views are shown in figure 2

