

www.FirstRanker.com

www.FirstRanker.com

Code No: RT22035

R13

SET - 1

II B. Tech II Semester Supplementary Examinations, November-2018 MACHINE DRAWING

(Com. to ME, AME, MM)

Time: 3 hours Max. Marks: 70

Note: 1. Question Paper consists of two parts (Part-A and Part-B)

2. Answer TWO question from Part-A

3. **Part-B** is compulsory

PART -A

1. Sketch the following: (11M)
a) BSW thread b) Buttren thread c) Internal threads d) Compression spring

- 2. Draw the sectional front view and side view of a cotter joint with sleeve used to (11M) connect two rods of 40 mm diameter each.
- 3. Draw (a) sectional view from the front and (b) view from above, of single (11M) riveted, double strap butt joint of thickness 15 mm:

PART -B

- 4. The part drawings of Stuffing box are shown in Fig. Assemble the parts and (48M) draw,
 - (i) Sectional view from the front and (ii) view from above.


1 of 2





Code No: RT22035


R13


SET - 1











Parts list

Part No.	Name	Matl	Qty
1	Body	CI	1
2	Gland	Brass	1
3	Bush	Brass	1
4	Stud	MS	2
5	Nut, M12	MS	2

Stuffing box