

#### www.FirstRanker.com

www.FirstRanker.com

Code No: R22036

**R10** 

**SET - 1** 

# II B. Tech II Semester Supplementary Examinations, November-2017 MACHINE DRAWING

(Com. to ME, AME)

Time: 3 hours Max. Marks: 75

## Note: Part A: Answer any TWO of the following questions:

**PART-B** is compulsory.

#### **PART-A**

 $(12.5M \times 2 = 25M)$ 

- 1. Draw any four type of set screws.
- 2. Draw the sectional front view of foot step bearing.
- 3. Two square rods of side 50 mm each are connected by a cotter joint with a gib. Sketch the half sectional front view and side view.

### **PART-B**


(50M)

4. Draw the assembled plan of the half sectional view of the horizontal cross head parts.

MMM.FirstRanker.com



**R10 SET** - 1 Code No: R22036



			.60
Item	Description	Qty.	Material
1	Body	1	C.S.
2	Shoe	2	C.I.
3	Piston rod	1,5	Steel
4	Cotter	1/2	M.S.
5	Pin	1	Steel